

Time	Priority	Description
2018-08-07, 12:08:44	Warning (5)	Dynamic Range Window violation
2018-08-07, 12:08:44	Warning (5)	RNG-RSP CCAP Commanded Power in Excess of 6 dB Below the Value Corresponding to the Top of the DRW;CM-MAC=a0:04:60:fc:b8:c0;CMTS-MAC=2c:86:d2:89:bd:5c;CM-QOS=1.1;CM-VER=3.1;
2018-08-07, 12:08:24	Warning (5)	Dynamic Range Window violation
2018-08-07, 12:08:24	Warning (5)	RNG-RSP CCAP Commanded Power in Excess of 6 dB Below the Value Corresponding to the Top of the DRW;CM-MAC=a0:04:60:fc:b8:c0;CMTS-MAC=2c:86:d2:89:bd:5c;CM-QOS=1.1;CM-VER=3.1;
2018-08-07, 12:08:24	Warning (5)	Dynamic Range Window violation
2018-08-07, 12:08:24	Warning (5)	RNG-RSP CCAP Commanded Power in Excess of 6 dB Below the Value Corresponding to the Top of the DRW;CM-MAC=a0:04:60:fc:b8:c0;CMTS-MAC=2c:86:d2:89:bd:5c;CM-QOS=1.1;CM-VER=3.1;
2018-08-07, 12:08:04	Warning (5)	Dynamic Range Window violation
2018-08-07, 12:08:04	Warning (5)	RNG-RSP CCAP Commanded Power in Excess of 6 dB Below the Value Corresponding to the Top of the DRW;CM-MAC=a0:04:60:fc:b8:c0;CMTS-MAC=2c:86:d2:89:bd:5c;CM-QOS=1.1;CM-VER=3.1;
2018-08-07, 12:08:04	Warning (5)	Dynamic Range Window violation
2018-08-07, 12:08:04	Warning (5)	RNG-RSP CCAP Commanded Power in Excess of 6 dB Below the Value Corresponding to the Top of the DRW;CM-MAC=a0:04:60:fc:b8:c0;CMTS-MAC=2c:86:d2:89:bd:5c;CM-QOS=1.1;CM-VER=3.1;
2018-08-07, 12:08:04	Warning (5)	Dynamic Range Window violation
2018-08-07, 12:08:04	Warning (5)	RNG-RSP CCAP Commanded Power in Excess of 6 dB Below the Value Corresponding to the Top of the DRW;CM-MAC=a0:04:60:fc:b8:c0;CMTS-MAC=2c:86:d2:89:bd:5c;CM-QOS=1.1;CM-VER=3.1;
2018-08-07, 12:07:44	Warning (5)	Dynamic Range Window violation
2018-08-07, 12:07:44	Warning (5)	RNG-RSP CCAP Commanded Power in Excess of 6 dB Below the Value Corresponding to the Top of the DRW;CM-MAC=a0:04:60:fc:b8:c0;CMTS-MAC=2c:86:d2:89:bd:5c;CM-QOS=1.1;CM-VER=3.1;
2018-08-07, 12:07:44	Warning (5)	Dynamic Range Window violation
2018-08-07, 12:07:44	Warning (5)	RNG-RSP CCAP Commanded Power in Excess of 6 dB Below the Value Corresponding to the Top of the DRW;CM-MAC=a0:04:60:fc:b8:c0;CMTS-MAC=2c:86:d2:89:bd:5c;CM-QOS=1.1;CM-VER=3.1;
2018-08-07, 12:07:44	Warning (5)	Dynamic Range Window violation
2018-08-07, 12:07:44	Warning (5)	RNG-RSP CCAP Commanded Power in Excess of 6 dB Below the Value Corresponding to the Top of the DRW;CM-MAC=a0:04:60:fc:b8:c0;CMTS-MAC=2c:86:d2:89:bd:5c;CM-QOS=1.1;CM-VER=3.1;
2018-08-07, 12:07:24	Warning (5)	Dynamic Range Window violation
2018-08-07, 12:07:24	Warning (5)	RNG-RSP CCAP Commanded Power in Excess of 6 dB Below the Value Corresponding to the Top of the DRW;CM-MAC=a0:04:60:fc:b8:c0;CMTS-MAC=2c:86:d2:89:bd:5c;CM-QOS=1.1;CM-VER=3.1;
2018-08-07, 12:07:24	Warning (5)	Dynamic Range Window violation
2018-08-07, 12:07:24	Warning (5)	RNG-RSP CCAP Commanded Power in Excess of 6 dB Below the Value Corresponding to the Top of the DRW;CM-MAC=a0:04:60:fc:b8:c0;CMTS-MAC=2c:86:d2:89:bd:5c;CM-QOS=1.1;CM-VER=3.1;
2018-08-07, 12:07:04	Warning (5)	Dynamic Range Window violation
2018-08-07, 12:07:04	Warning (5)	RNG-RSP CCAP Commanded Power in Excess of 6 dB Below the Value Corresponding to the Top of the DRW;CM-MAC=a0:04:60:fc:b8:c0;CMTS-MAC=2c:86:d2:89:bd:5c;CM-QOS=1.1;CM-VER=3.1;
2018-08-07, 12:06:26	Critical (3)	Started Unicast Maintenance Ranging - No Response received - T3 time-out;CM-MAC=a0:04:60:fc:b8:c0;CMTS-MAC=2c:86:d2:89:bd:5c;CM-QOS=1.1;CM-VER=3.1;
2018-08-07, 12:06:24	Warning (5)	Dynamic Range Window violation
2018-08-07, 12:06:24	Warning (5)	RNG-RSP CCAP Commanded Power in Excess of 6 dB Below the Value Corresponding to the Top of the DRW;CM-MAC=a0:04:60:fc:b8:c0;CMTS-MAC=2c:86:d2:89:bd:5c;CM-QOS=1.1;CM-VER=3.1;
2018-08-07, 12:06:24	Warning (5)	Dynamic Range Window violation
2018-08-07, 12:06:24	Warning (5)	RNG-RSP CCAP Commanded Power in Excess of 6 dB Below the Value Corresponding to the Top of the DRW;CM-MAC=a0:04:60:fc:b8:c0;CMTS-MAC=2c:86:d2:89:bd:5c;CM-QOS=1.1;CM-VER=3.1;
2018-08-07, 12:06:24	Warning (5)	Dynamic Range Window violation
2018-08-07, 12:06:24	Warning (5)	RNG-RSP CCAP Commanded Power in Excess of 6 dB Below the Value Corresponding to the Top of the DRW;CM-MAC=a0:04:60:fc:b8:c0;CMTS-MAC=2c:86:d2:89:bd:5c;CM-QOS=1.1;CM-VER=3.1;

2018-08-07, 12:06:24	Warning (5)	Dynamic Range Window violation
2018-08-07, 12:06:24	Warning (5)	RNG-RSP CCAP Commanded Power in Excess of 6 dB Below the Value Corresponding to the Top of the DRW;CM-MAC=a0:04:60:fc:b8:c0;CMTS-MAC=2c:86:d2:89:bd:5c;CM-QOS=1.1;CM-VER=3.1;
2018-08-07, 11:22:49	Notice (6)	CM-STATUS message sent. Event Type Code: 3; Chan ID: N/A; DSID: q; MAC Addr: N/A; OFDM/OFDMA Profile ID: N/A.;CM-MAC=a0:04:60:fc:b8:c0;CMTS-MAC=2c:86:d2:89:bd:5c;CM-QOS=1.1;CM-VER=3.1;
2018-08-07, 11:22:49	Warning (5)	Unicast DSID PSN startup error
2018-08-07, 11:21:16	Warning (5)	REG-RSP-MP Mismatch Between Calculated Value for P1.6hi Compared to CCAP Provided Value;CM-MAC=a0:04:60:fc:b8:c0;CMTS-MAC=2c:86:d2:89:bd:5c;CM-QOS=1.1;CM-VER=3.1;
2018-08-07, 11:21:11	Notice (6)	DS profile assignment change. DS Chan ID: 32; Previous Profile: ; New Profile: 1 ;CM-MAC=a0:04:60:fc:b8:c0;CMTS-MAC=2c:86:d2:89:bd:5c;CM-QOS=1.1;CM-VER=3.1;
Time Not Established	Notice (6)	Honoring MDD; IP provisioning mode = IPv6
Time Not Established	Critical (3)	No Ranging Response received - T3 time-out;CM-MAC=a0:04:60:fc:b8:c0;CMTS-MAC=2c:86:d2:89:bd:5c;CM-QOS=1.1;CM-VER=3.1;
Time Not Established	Critical (3)	SYNC Timing Synchronization failure - Failed to acquire QAM/QPSK symbol timing;CM-MAC=a0:04:60:fc:b8:c0;CMTS-MAC=00:00:00:00:00:00;CM-QOS=1.1;CM-VER=3.1;